



Department of Energy
Washington, DC 20585

January 25, 2010

Kiran Patel
AAAA World Import-Export, Inc.
7800 NW 29th Street
Miami, FL 33122-1104

Dear Mr. Patel,

The purpose of this letter is to notify you that the AAAA World Import-Export compact fluorescent lamps (CFLs), models **HS14BX3** and **HS14CL3**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. The disqualification of these products is a result of the PEARL Cycle 9 testing indicating the products failed to meet ENERGY STAR criteria (*as noted in the letter to your supplier, Xiamen Longstar, dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

AAAA World Import-Export must stop sale and shipment of these products bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to these products. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify these models, AAAA World Import-Export should work to make the necessary improvements to their design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about these products' disqualification. Retailers will be asked to remove these products from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A handwritten signature in black ink that reads "Scott Harris". The signature is stylized with a large, sweeping "S" and a distinct "H".

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Alex Ham
Buffalo Lite
2665 Temple Ave.
Signal Hill, CA 90755

Dear Mr. Ham,

The purpose of this letter is to notify you that the Buffalo Lite compact fluorescent lamp (CFL), model **2214**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Buffalo Lite must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Buffalo Lite should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A handwritten signature in black ink that reads "Scott Harris". The signature is stylized with a large, sweeping "S" and a cursive "Harris".

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Brian Currie
Canadian Tire
2180 Yonge Street
13th Floor South
Toronto, ON M4P 2V8
Canada

Dear Mr. Currie,

The purpose of this letter is to notify you that the Canadian Tire compact fluorescent lamp (CFL), model **052-5391-4**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Canadian Tire must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Canadian Tire should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.


If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A handwritten signature in black ink that reads "Scott Harris". The signature is stylized with a large, sweeping "S" and a cursive "Harris".

Scott Blake Harris
General Counsel





Department of Energy

Washington, DC 20585

January 25, 2010

Cheuk Yuet
CNA International
#8 - 8980 Fraserwood Court
Burnaby, BC V5J 5H7
Canada

Dear Mr. Yuet,

The purpose of this letter is to notify you that the CNA International compact fluorescent lamp (CFL), model **EST-14W**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

CNA International must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, CNA International should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.


Sincerely,

A handwritten signature in black ink that reads "Scott Harris".

Scott Blake Harris
General Counsel



Printed with soy ink on recycled paper



Department of Energy
Washington, DC 20585

January 25, 2010

Marcel Pilon
Conglom, Inc.
4600 Poirier Blvd.
Saint Laurent, QC H4R2C5
Canada

Dear Mr. Pilon,

The purpose of this letter is to notify you that the Conglom compact fluorescent lamp (CFL), model **P-17752**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Conglom must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Conglom should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A stylized, handwritten signature of Scott Blake Harris in black ink.

Scott Blake Harris
General Counsel



Printed with soy ink on recycled paper



Department of Energy
Washington, DC 20585

January 25, 2010

Rizwan Haroon Parekh
Cyber Tech Lighting
1301 E. Wilshire Ave
Santa Ana, CA 92704

Dear Mr. Parekh,

The purpose of this letter is to notify you that the Cyber Tech Lighting compact fluorescent lamp (CFL), model **P14XSP/WW**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Cyber Tech Lighting must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Cyber Tech Lighting should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.


If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A stylized, handwritten signature in black ink that reads "Scott Harris". The signature is written in a cursive, flowing style.

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Vince Slack
Do It Best
6502 Nelson Road
Fort Wayne, IN 46803

Dear Mr. Slack,

The purpose of this letter is to notify you that the Do It Best compact fluorescent lamp (CFL), model **FE-IISB-14W-WV**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Do It Best must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Do It Best should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.


If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A handwritten signature in black ink that reads "Scott Harris". The signature is stylized with a large, sweeping "S" and a circular flourish at the end of the name.

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Aaron Feit
Feit Electric
4901 Gregg Road
Pico Rivera, CA 90660-2108

Dear Mr. Feit,

The purpose of this letter is to notify you that the Feit Electric compact fluorescent lamps (CFLs), models **BPESL15T/DM**, **BPESL14T2/2(l)**, and **ESL15R30TM**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. The disqualification of these products is a result of the PEARL Cycle 9 testing indicating the products failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Feit Electric must stop sale and shipment of these products bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to these products. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify these models, Feit Electric should work to make the necessary improvements to their design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about these products' disqualification. Retailers will be asked to remove these products from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.


If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A stylized, handwritten signature in black ink that reads "Scott Harris".

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Rich Channell
Fred's Inc.
4300 New Getwell Rd.
Memphis, TN 38118

Dear Mr. Channell,

The purpose of this letter is to notify you that the Fred's Inc. compact fluorescent lamps (CFLs), models **12168**, **12143**, and **12171**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. The disqualification of these products is a result the PEARL Cycle 9 testing indicating the products failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Fred's Inc. must stop sale and shipment of these products bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to these products. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify these models, Fred's Inc. should work to make the necessary improvements to their design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about these products' disqualification. Retailers will be asked to remove these products from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.


If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A handwritten signature in black ink that reads "Scott Harris".

Scott Blake Harris
General Counsel





Department of Energy

Washington, DC 20585

January 25, 2010

Thomas Cohen
Greenlite
10 Corporate Park
Suite 100
Irvine, CA 92606

Dear Mr. Cohen,

The purpose of this letter is to notify you that the Greenlite compact fluorescent lamp (CFL), model **14W/ELS-U/1**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Greenlite must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Greenlite should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A stylized, handwritten signature in black ink that reads "Scott Harris". The signature is written in a cursive, slightly slanted font.

Scott Blake Harris
General Counsel



Printed with soy ink on recycled paper



Department of Energy
Washington, DC 20585

January 25, 2010

Jason Cook
Howard Industries
580 Eastview Drive
Laurel, MS 39440

Dear Mr. Cook,

The purpose of this letter is to notify you that the Howard Industries compact fluorescent lamp (CFL), model **CF14MS/827**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Howard Industries must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Howard Industries should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A stylized, handwritten signature in black ink that reads "Scott Harris".

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Neeraj Gupta
Hudson's Bay
8925 Torbram Rd
Brampton, ON L6T 4G1
Canada

Dear Neeraj Gupta,

The purpose of this letter is to notify you that the Hudson's Bay compact fluorescent lamp (CFL), model **T2-14W-WW-10-2**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Hudson's Bay must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Hudson's Bay should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.


Sincerely,

A stylized, handwritten signature of Scott Blake Harris in black ink.

Scott Blake Harris
General Counsel



Printed with soy ink on recycled paper



Department of Energy
Washington, DC 20585

January 25, 2010

David Soncrant
Kroger Company
3800 SE 22nd Ave
Portland, OR 97202

Dear Mr. Soncrant,

The purpose of this letter is to notify you that the Kroger compact fluorescent lamp (CFL), model **2814-BXEL**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Kroger must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Kroger should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.


If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A stylized, handwritten signature of Scott Blake Harris in black ink.

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Joanna Kavouris
L'Image Home Products
1175 Place Du Frere Andre
Montreal, QC H3B 3X9
Canada

Dear Ms. Kavouris,

The purpose of this letter is to notify you that the L'Image Home Products compact fluorescent lamps (CFLs), models **11799, 11800, 11671, and 11985**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. The disqualification of these products is a result of the PEARL Cycle 9 testing indicating the products failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

L'Image Home Products must stop sale and shipment of these products bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to these products. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify these models, L'Image Home Products should work to make the necessary improvements to their design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about these products' disqualification. Retailers will be asked to remove these products from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A handwritten signature in black ink that reads "Scott Harris".

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Sandeep Sood
Litetronics International
4101 W. 123rd Street
Alsip, IL 60803

Dear Mr. Sood,

The purpose of this letter is to notify you that the Litetronics compact fluorescent lamp (CFL), model **EL-14527**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Litetronics must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Litetronics should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.


If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A handwritten signature in black ink that reads "Scott Harris". The signature is stylized with a large, sweeping "S" and a cursive "Harris".

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Mohammed Razzak
Lights of America
611 Reyes Drive
Walnut, CA 91789

Dear Mr. Razzak,

The purpose of this letter is to notify you that the Lights of America compact fluorescent lamp (CFL), model **2814L**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Lights of America must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Lights of America should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.


If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A handwritten signature in black ink that reads "Scott Harris". The signature is stylized with a large, bold "S" and a cursive "Harris".

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Jet Li
Xiamen Longstar Lighting Company, Ltd.
Cheng Nan Industrial Zone
Tong An Xiamen, Fujian 361100
China

Dear Mr. Li,

The purpose of this letter is to notify you that the Xiamen Longstar's compact fluorescent lamp (CFL), model **FE-IISB-14W**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your private labeler's products will be disqualified as well.

Xiamen Longstar must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Xiamen Longstar should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A stylized, handwritten signature of Scott Blake Harris in black ink.

Scott Blake Harris
General Counsel



Printed with soy ink on recycled paper



Department of Energy

Washington, DC 20585

January 25, 2010

Jason Warner
Lowe's Companies
1000 Lowe's Blvd
 Mooresville, NC 28117

Dear Mr. Warner,

The purpose of this letter is to notify you that the Lowe's compact fluorescent lamp (CFL), model **80424 (retail # LBP15R30M2)**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Lowe's must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Lowe's should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A stylized, handwritten signature of Scott Blake Harris in black ink.

Scott Blake Harris
General Counsel



Printed with soy ink on recycled paper



Department of Energy
Washington, DC 20585

January 25, 2010

Greg Murphy
Maxlite
80 Little Falls Road
Fairfield, NJ 07004

Dear Mr. Murphy,

The purpose of this letter is to notify you that the Maxlite compact fluorescent lamps (CFLs), models **HCS14T2WW** and **MLS14T2WW**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. The disqualification of these products is a result of the PEARL Cycle 9 testing indicating the products failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Maxlite must stop sale and shipment of these products bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to these products. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify these models, Maxlite should work to make the necessary improvements to their design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about these products' disqualification. Retailers will be asked to remove these products from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A stylized, handwritten signature of Scott Harris in black ink.

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Adam Cameron
Silk Ventures Group
11A Fui Nam Building, 48-51 Connaught Road West
Hong Kong 310002
China

Dear Mr. Cameron,

The purpose of this letter is to notify you that the Silk Ventures Group compact fluorescent lamp (CFL), model **FE-IISB-14W**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Silk Ventures Group must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Silk Ventures Group should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A handwritten signature in black ink that reads "Scott Harris". The signature is stylized with a large "S" and a circular flourish at the end.

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Kevin Xu
Topstar International
20529 E Walnut Drive N
Walnut, CA 91789

Dear Mr. Xu,

The purpose of this letter is to notify you that the Topstar compact fluorescent lamp (CFL), model **CFLT2MS-14W**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your private labeler's product will be disqualified as well.

Topstar must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Topstar should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A handwritten signature in black ink that reads "Scott Harris".

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Eddy Spivak
Turolight Inc.
820 Flint Road
North York, ON M3J 2J5
Canada

Dear Mr. Spivak,

The purpose of this letter is to notify you that the Turolight compact fluorescent lamp (CFL), model **TL-EDGE14**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Turolight must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Turolight should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A handwritten signature in black ink that reads "Scott Harris". The signature is stylized with a large, bold "S" and a cursive "Harris".

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

David Lu
U Lighting America
3/F, Liming Building, No. 144
Zhongxing Road
Shezhen 518001
China

Dear Mr. Lu,

The purpose of this letter is to notify you that the U Lighting compact fluorescent lamp (CFL), model **SDS-15W**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging will be disqualified as well.

U Lighting must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, U Lighting should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A handwritten signature in black ink that reads "Scott Harris". The signature is stylized with a large, bold "S" and a cursive "Harris".

Scott Blake Harris
General Counsel





Department of Energy
Washington, DC 20585

January 25, 2010

Ronald Benedict
Uninex International
5780 Smithway Street
Commerce, CA 90040

Dear Mr. Benedict,

The purpose of this letter is to notify you that the Uninex compact fluorescent lamp (CFL), model **KL1914**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your supplier's product will be disqualified as well.

Uninex must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Uninex should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.


If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

A handwritten signature in black ink that reads "Scott Harris". The signature is stylized with a large, bold "S" and a cursive "Harris".

Scott Blake Harris
General Counsel





Department of Energy

Washington, DC 20585

January 25, 2010

Jeff Shen
Zhejiang Yankon Group Co., Ltd
No. 129 Fengshan Road
Shang Yu, Zhejiang 312300
China

Dear Mr. Shen,

The purpose of this letter is to notify you that the Zhejiang Yankon Group's compact fluorescent lamp (CFL), model **FE172 13S**, will be disqualified from the ENERGY STAR Program, effective today, **January 25, 2010**. This product disqualification is a result of the PEARL Cycle 9 testing indicating the product failed to meet ENERGY STAR criteria (*as noted in the letter to Osram Sylvania dated November 2, 2009, from Richard Karney, ENERGY STAR Products Manager*). When a product is disqualified from the ENERGY STAR program, all corresponding packaging and your private labeler's products will be disqualified as well.

Yankon must stop sale and shipment of this product bearing the ENERGY STAR certification mark and must cease use of the ENERGY STAR mark on web pages and other marketing materials related to this product. The ENERGY STAR Program Requirements for CFLs Partner Commitments provides the specific actions necessary to stay in compliance with the program.

In order to re-qualify this model, Yankon should work to make the necessary improvements to the product design or manufacturing process and resubmit all completed test reports, qualification forms and corresponding packaging proofs demonstrating full compliance with the current ENERGY STAR criteria for CFLs.

ENERGY STAR retail and energy efficiency program sponsor partners will be notified about this product's disqualification. Retailers will be asked to remove this product from their shelves or cover the ENERGY STAR mark on product packaging within 90 days of the effective date of disqualification. The Department encourages you to work with your retailers and distributors to ensure that these steps are taken as expeditiously as possible.

If you have any questions about this letter, please feel free to contact Richard Karney at richard.karney@ee.doe.gov.

Sincerely,

Scott Blake Harris
General Counsel

