














Note:
GIS layers provided by The Boeing Company
February 2008
















Note:
GIS layers provided by The Boeing Company
February 2008




Santa Susana Field Laboratory Area IV
Ventura County, California



Note:
GIS layers provided by The Boeing Company
February 2008








Note:
GIS layers provided by The Boeing Company
February 2008





Santa Susana Field Laboratory Area IV
Ventura County, California




































Note:
GIS layers provided by The Boeing Company
February 2008





Note:
GIS layers provided by The Boeing Company
February 2008




Santa Susana Field Laboratory Area IV
Ventura County, California

Figure F5-10
Dioxin COIs in Soils - EU-05
(2-10 ft bgs)









Note:
GIS layers provided by The Boeing Company
February 2008



Santa Susana Field Laboratory Area IV
Ventura County, California

Figure F6-1
VOC COIs in Soils - EU-06
(0-2 ft bgs)







Note:
GIS layers provided by The Boeing Company
February 2008





Santa Susana Field Laboratory Area IV
Ventura County, California

Figure F6-3
PCB COIs in Soils - EU-06
(0-2 ft bgs)













Note:
GIS layers provided by The Boeing Company
February 2008



Note:
GIS layers provided by The Boeing Company
February 2008











Santa Susana Field Laboratory Area IV
Ventura County, California


Figure F6-11
Radiological COIs in Soils - EU-06
(0-6 in bgs)


























Note:
GIS layers provided by The Boeing Company
February 2008








Note:
GIS layers provided by The Boeing Company
February 2008




Santa Susana Field Laboratory Area IV
Ventura County, California


Figure F7-11
Radiological COIs in Soils - EU-07
(0-6 in bgs)





Santa Susana Field Laboratory Area IV
Ventura County, California


Figure F8-0
EU-08 Chemical Use Areas

































Santa Susana Field Laboratory Area IV
Ventura County, California


Figure F8-11
Radiological COIs in Soils - EU-08
(0-6 in bgs)

















Note:
GIS layers provided by The Boeing Company
February 2008




Note:
GIS layers provided by The Boeing Company
February 2008





Note:
GIS layers provided by The Boeing Company
February 2008





Note:
GIS layers provided by The Boeing Company
February 2008










































Santa Susana Field Laboratory Area IV
Ventura County, California


Figure F11-0
EU-11 Chemical Use Areas



Note:
GIS layers provided by The Boeing Company
February 2008



Santa Susana Field Laboratory Area IV
Ventura County, California





Note:
GIS layers provided by The Boeing Company
February 2008



Santa Susana Field Laboratory Area IV
Ventura County, California

Figure F11-2
SVOC COIs in Soils - EU-11
(0-2 ft bgs)







Note:
GIS layers provided by The Boeing Company
February 2008




Santa Susana Field Laboratory Area IV
Ventura County, California

Figure F11-4
Inorganic COIs in Soils - EU-11
(0-2 ft bgs)









Note:
GIS layers provided by The Boeing Company
February 2008




Santa Susana Field Laboratory Area IV
Ventura County, California



Note:
GIS layers provided by The Boeing Company
February 2008






Note:
GIS layers provided by The Boeing Company
February 2008



Santa Susana Field Laboratory Area IV
Ventura County, California

Figure F11-10
Dioxin COIs in Soils - EU-11
(2-10 ft bgs)



Note:
GIS layers provided by The Boeing Company
February 2008



Santa Susana Field Laboratory Area IV
Ventura County, California

Figure F11-11
Radiological COIs in Soils - EU-11
(0-6 in bgs)

