


RECENT GROUNDWATER MONITORING RESULTS



Explanation

- Chatsworth Monitoring Well
- ▣ Chatsworth Extraction Well
- Property Boundary Line
- Location of Recently Constructed Well
- ND Not Detected; for Tritium - Less than Minimum Detectable Activity
- VOCs in ug/l; Tritium in pCi/l



UNDERGROUND
ENGINEERING &
ENVIRONMENTAL
SOLUTIONS

THE BOEING COMPANY
ROCKETDYNE PROPULSION & POWER
SANTA SUSANA FIELD LABORATORY

WATER QUALITY RESULTS WELLS RD-90, RD-91, AND RD-92

SCALE AS SHOWN

JUNE 2004

FIGURE 1

106_SSFL_AREA_IV_RAD_WELLS