

Community Outreach Network

Uranium and Radiation
on the Navajo Nation2026
2027

Topic	Agency, Program, and Location	Telephone Number	
Mines and structures			
Cleanup of chemical and radiological hazards at abandoned uranium mines (AUM)	U.S. Environmental Protection Agency (EPA), Region 9 Superfund Program, San Francisco, California	(800) 231-3075	
		(505) 240-0093	Eastern AUM region Southern AUM region
		(480) 250-0990	North central AUM region Northern AUM region Central AUM region
	Navajo Nation EPA (NNEPA), Navajo Superfund Program, Window Rock, Arizona	(928) 310-4854 (928) 871-7325	Western AUM region
Contaminated structures	NNEPA, Navajo Superfund Program, Window Rock, Arizona, Contaminated Structures Program	(928) 871-7325	
Address physical hazards to abandoned mine lands such as copper, sand, and gravel pits	Navajo Abandoned Mine Lands (AML) Reclamation/Uranium Mill Tailings Remedial Action (UMTRA) Department	(928) 871-6982	Window Rock, Arizona
		(505) 368-1228	Shiprock, New Mexico
		(928) 283-3188	Tuba City, Arizona
Radon in your home and radon test kits	NNEPA, Radon Program, Air and Toxics Department, Window Rock, Arizona	(928) 871-7692 (928) 871-7703	
Uranium mill sites			
Disposal sites — long-term surveillance and maintenance (LTS&M)	U.S. Department of Energy (DOE) Office of Legacy Management (LM), Grand Junction, Colorado	(970) 248-6621	Mexican Hat, Utah
		(505) 587-2149	Shiprock, New Mexico
		(928) 810-2100	Tuba City, Arizona
Former processing site — LTS&M	U.S. DOE LM, Grand Junction, Colorado	(505) 587-2149	Monument Valley, Arizona
Disposal sites — general licensing and oversight	U.S. Nuclear Regulatory Commission (NRC), Washington, D.C.	(800) 368-5642	
Former processing site — oversight	NRC, Washington, D.C.	(800) 368-5642	



Topic	Agency, Program, and Location	Telephone Number
Health		
Preventive health information	Navajo Department of Health (NDOH), Community Health Representative/Outreach Program, Window Rock, Arizona	(928) 871-6875
Exposure prevention education	Agency for Toxic Substances and Disease Registry (ATSDR) Region 9	(415) 290-0680
Uranium medical screening and monitoring program (for community members)	Community Uranium Exposure — Journey to Healing Program, Northern Navajo Medical Center, Shiprock, New Mexico	(505) 368-7054 or (505) 368-7032
Radiation Exposure Screening and Education Program (RESEP) — Medical screening (for uranium workers)	North County Healthcare RESEP, Flagstaff, Arizona	(928) 522-9427
	Northern Navajo RESEP, Shiprock, New Mexico	(505) 368-7054 or (505) 368-7032
	Tuba City Regional Health Care Corporation RESEP	(928) 283-1802
Navajo Birth Cohort Study	University of New Mexico, Albuquerque, New Mexico	(877) 545-6775
Local oncology specialty services	Tuba City Regional Health Care Corporation, Specialty Care Center, Tuba City, Arizona	(928) 283-2402
Hopi cancer assistance fund	Hopi Cancer Support Services (HCSS) Hopi Tribe Department of Health and Human Services	(928) 734-1151

Uranium compensation claims assistance

Radiation Exposure Compensation Act (RECA): Claims assistance includes all uranium workers from 1990 and before as well as downwinders	Northern Navajo RESEP, Shiprock, New Mexico	(505) 368-7054 or (505) 368-7032
	North County Healthcare RESEP, Flagstaff, Arizona	(928) 522-9427
	Office of Navajo Uranium Workers, Shiprock, New Mexico	(505) 368-1260 or (505) 368-1266
	Tuba City Regional Health Care Corp RESEP, Tuba City, Arizona	(928) 283-1802
Energy Employees Occupational Illness Compensation Program Act (EEOICPA) claims assistance for any uranium workers	Northern Navajo RESEP, Shiprock, New Mexico	(505) 368-7054 or (505) 368-7032

Uranium policy advisory and additional resources

Studies the impact of uranium mining and milling on Navajo lands and provides recommendations to Navajo Nation President and counsel for policies, law, and regulations.	Diné Uranium Remediation Advisory Commission (DURAC), Window Rock, Arizona	(928) 318-4990
--	--	----------------



Topic	Agency, Program, and Location	Telephone Number
Educational Programs		
Environmental and Ecological risk assessment; traditional ecological knowledge	Diné Environmental Consultant and Education LLC, Shiprock, New Mexico	(505) 406-0947
Water		
Water hauling practices for safe drinking water sources	NNEPA, Public Water Systems Supervision Program, Window Rock, Arizona	(928) 871-7755
Locations of regulated watering points	Navajo Tribal Utility Authority (NTUA), Fort Defiance, Arizona	(800) 528-5011
Water quality of NTUA piped water for home or public water system	NTUA, Fort Defiance, Arizona	(928) 729-6207 Ask for "Consumer Confidence Report"
Surface- and groundwater quality	NNEPA, Water Quality Program, Window Rock, Arizona	(928) 871-7185 Fort Defiance, Chinle (505) 368-1037 Northern, Eastern (928) 890-7599 Western
Operation and maintenance of livestock water sources Locations of unregulated sources, livestock wells, windmills, earthen dams	Navajo Department of Water Resources (NDWR), Technical, Construction, and Operations Branch	(928) 729-4032 (928) 729-4003 Fort Defiance
Tuba City Disposal Site		
Bureau of Indian Affairs (BIA) coordination	BIA Division of Environmental Services and Cultural Resources Management, Albuquerque, New Mexico	(505) 563-3313
BIA Navajo Regional Office	BIA, Navajo Regional Office, Gallup, New Mexico	(505) 863-8314
Hopi Tribal water	Hopi Tribe, Water Resources Program, Kykotsmovi, Arizona	(928) 734-3712
Remedial investigation and feasibility study oversight	EPA, Region 9 Superfund Program, San Francisco, California	(800) 231-3075
Navajo Nation Solid Waste Act	NNEPA, Resource Conservation & Recovery Program, Window Rock, Arizona	(928) 871-7816

Abbreviations

AML	abandoned mine lands
ATSDR	Agency for Toxic Substances and Disease Registry
AUM	abandoned uranium mine
BIA	Bureau of Indian Affairs
DURAC	Diné Uranium Remediation Advisory Commission
EPA	U.S. Environmental Protection Agency
EEOICPA	Energy Employees Occupational Illness Compensation Program Act
LM	U.S. Department of Energy Office of Legacy Management
LTS&M	long-term surveillance and maintenance

NAIHS	Navajo Area Indian Health Service
NDOH	Navajo Department of Health
NDWR	Navajo Department of Water Resources
NNEPA	Navajo Nation Environmental Protection Agency
NRC	U.S. Nuclear Regulatory Commission
NTUA	Navajo Tribal Utility Authority
RECA	Radiation Exposure Compensation Act
RESEP	Radiation Exposure Screening and Education Program
UMTRA	Uranium Mill Tailing Remedial Action Program



Contact Information

For more information about Community Outreach Network and its activities at the Window Rock office, contact:

Shine K. Salt
Public Affairs Tribal Specialist/Community Outreach Network Liaison

Office Number:
(970) 200-4607

Email:
shine.salt@lm.doe.gov

U.S. Department of Energy
Office of Legacy Management
Highway 264 & Indian Route 12, Suite 10
Window Rock, AZ 86515

Office Hours:
9 a.m. to 4 p.m. (open to the public)

Website:
<https://www.epa.gov/navajo-nation-uranium-cleanup>

Ten-Year Plan:
<https://www.epa.gov/navajo-nation-uranium-cleanup/federal-plans>