Fact Sheet





Attleboro, Massachusetts, Site A FUSRAP site

This fact sheet provides information about the **Attleboro site**. Long-term stewardship responsibilities for this site are managed by the **U.S. Department of Energy Office of Legacy Management** under the **Formerly Utilized Sites Remedial Action Program**.

Site Information and History 🗈 💵

The Attleboro, Massachusetts, Site (formerly the Shpack Landfill Superfund Site) is a 9.4-acre property located on the border between Norton and Attleboro, Massachusetts. Approximately 6 acres is located within the town of Norton, and the remainder is located in Attleboro. A private landfill was operated at the site from 1946 through the 1970s, accepting domestic and industrial waste, including chemical and low-level radioactive waste.

The U.S. Nuclear Regulatory Commission (NRC) initiated an investigation of the Shpack landfill site on November 14, 1978, after receiving a telephone call from a concerned citizen. NRC's investigation concluded that material associated with nuclear fuel had been disposed of at the site from about 1957 to 1966. NRC found depleted uranium, as well as natural and enriched uranium at the landfill. NRC determined that the source of the uranium materials was probably contract work performed for the U.S. Atomic Energy Commission (AEC) by M&C Nuclear Inc., which merged with Texas Instruments Inc. in 1959.

The U.S. Department of Energy (DOE) initiated a radiological survey at the site in August 1980 and added it to the Formerly Utilized Sites Remedial Action Program (FUSRAP) for radiological cleanup in January 1981. The survey indicated the presence of radioactive materials throughout the landfill. The distribution of the contamination was found to be uneven and spotty, and, in many cases, extended into the groundwater. At the same time as the radiological survey, DOE conducted an interim remedial action under their regulatory authority to remove 800 to 900 pounds of drummed radioactive waste.

In 2002, the U.S. Army Corps of Engineers (USACE) initiated a detailed gamma walkover survey, environmental sampling, and analysis effort to characterize the radiological contaminants of concern. USACE determined that some of the radiological contamination was not a result of AEC activities and, therefore, not eligible for FUSRAP. Congress passed legislation authorizing cleanup of all remaining non-FUSRAP radiological contaminants of concern. USACE remediation activities at the site included installing and constructing temporary facilities, site infrastructure, and test pits; excavating and characterizing waste; constructing earth-shoring supports; collecting postexcavation confirmatory samples; backfilling; and packaging and shipping low-activity radioactive waste for off-site disposal. USACE excavated 57,805 cubic yards of material — 50,908 cubic yards of which were transported off-site for disposal.

Multiple overhead transmission lines owned by National Grid cross the site and low levels of inaccessible radioactive contamination remain under the power poles. Contact with the inaccessible soils is prevented by institutional controls (ICs) maintained by National Grid.

Regulatory Setting 🥭

AEC, the predecessor agency to DOE, established FUSRAP in March 1974 to evaluate radioactive contamination at sites used in the development of nuclear weapons and atomic energy programs. DOE has the authority, under the Atomic Energy Act (AEA) of 1954, to perform radiological surveys, monitoring, and maintenance at sites used to support the activities of its predecessor agencies. DOE also had authority under AEA to remediate FUSRAP sites identified as requiring some form of response action. In 1997, Congress transferred responsibility for FUSRAP site characterization and remediation from DOE to USACE. USACE had conducted these response actions in accordance with the Comprehensive Environmental Response, Compensation, and Liability Act of 1980, as amended, and the National Oil and Hazardous Substances Pollution Contingency Plan. The DOE Office of Legacy Management (LM) retains responsibility for longterm stewardship of remediated FUSRAP sites. For more information about the program, please see the FUSRAP fact sheet.

The site was added to the National Priorities List (NPL) in June 1986. An investigation into the nature and extent of the contamination began in 1990. Known as Performing Defendants, fourteen potentially responsible parties identified by the U.S. Environmental Protection Agency (EPA) entered into an Administrative Order on Consent with the EPA to address chemical and hazardous materials. USACE and DOE are not identified as Performing Defendants because they were not identified by EPA as potentially responsible parties for the chemical contamination. The selected remedy documented in the Record of Decision (ROD) was implemented in two parts. In August 2005, Operable Unit 1 (OU-1) addressed the FUSRAP-related radioactive contamination; beginning in June 2007, OU-2 addressed non-radiological contamination to be handled by the Performing Defendants following FUSRAP cleanup.

The implemented remedy achieved the degree of cleanup and protection specified in the ROD for all pathways of exposure. The ROD states that ICs are required to restrict future use of the property and groundwater for the site due to hazardous substances remaining on-site above levels that allow for unlimited use and unrestricted exposure.

USACE completed the FUSRAP remedial action in OU-1 in 2011, and the Performing Defendants completed the CERCLA remedial action in OU-2 in 2014. EPA declared that the entire site met cleanup requirements in November 2016, and the Massachusetts Department of Environmental Protection concurred. EPA removed the site from the NPL in September 2017.

In January 2019, USACE transferred long-term stewardship for the Attleboro site to LM.

Current Site Conditions 🌲

The site is currently maintained by the city of Attleboro. The majority of the site is grass covered with restored wetland. The city provides a continuing presence at the site for long-term monitoring and maintenance of the ICs.

Legacy Management Activities 📩

LM responsibilities are limited to managing site records and responding to stakeholder inquiries. The city of Attleboro performs groundwater monitoring, enforces groundwater ICs, and submits annual reports to EPA and the Massachusetts Department of Environmental Protection. National Grid is responsible for the ICs regarding inaccessible soil contamination and will be required to develop a soil management plan if these areas must be disturbed in the future. The ROD states that EPA will conduct the five-year reviews.

IN CASE OF AN EMERGENCY AT THE SITE, CONTACT 911

LM TOLL-FREE EMERGENCY HOTLINE: (877) 695-5322

Site-specific documents related to the **Attleboro**, **Massachusetts**, **Site** are available on the LM website at www.energy.gov/lm/attleboro-massachusetts-site

For more information on FUSRAP site history or current long-term stewardship activities, contact: U.S. Department of Energy Office of Legacy Management 2597 Legacy Way Grand Junction, CO 81503

Email: FUSRAPinfo@lm.doe.gov public.affairs@lm.doe.gov

DOE Office of Legacy Management (970) 248-6070

www.energy.gov/lm

- www.facebook.com/OfficeofLegacyManagement
- in www.linkedin.com/showcase/office-of-legacymanagement