

Appendix B.
Photographs

Appendix B. Photographs

Contents

Photos	Section.....	Page
1 – 4	Cell Excavation	B-1
5 - 30	RRM.....	B-3
31 - 36	Interim Cover	B-17
37 - 38	Spoils Embankment	B-20

Appendix B. Photographs – Cell Excavation



Photo 1. Cell Excavation September 2020



Photo 2. Cell Excavation September 2020

Appendix B. Photographs – Cell Excavation (*continued*)



Photo 3. Cell Excavation September 2020



Photo 4. Cell Excavation September 2020

Appendix B. Photographs – RRM



Photo 5. Bulldozer Pushing Material To Be Compacted October 2019



Photo 6. Placing and Hauling RRM October 2019

Appendix B. Photographs – RRM (continued)



Photo 7 RRM Lifts Scarified for Prior to Placement November 2019



Photo 8. Remaining Stockpile Placed November 2019

Appendix B. Photographs – RRM (continued)



Photo 9. Placing Material on Lift Areas December 2019



Photo 10. Dump Ramp Operations January 2020

Appendix B. Photographs – RRM (*continued*)



Photo 11. Two Foot Sacrificial Lift January 2020



Photo 12. Two Foot Sacrificial Lifts on Floor of Cell January 2019

Appendix B. Photographs – RRM (continued)



Photo 12. Walking Debris Lift Prior to Placing RRM February 2020



Photo 13. 825 Compacting RRM Lift with Sheepsfoot February 2020

Appendix B. Photographs – RRM (continued)



Photo 14. Compacting North Top of Seven Foot Lift March 2020



Photo 15. Final Top of Waste RRM Grade March 2020

Appendix B. Photographs – RRM (continued)



Photo 16. Bulldozer Placing Material April 2020



Photo 17. Debris Lift Ready for Compaction April 2020

Appendix B. Photographs – RRM (continued)



Photo 18-Cell Operations May2020



Photo 19. Moisture/Density Testing May 2020

Appendix B. Photographs – RRM (continued)



Photo 19. Cell Operations June 2020



Photo 20. Compacting RRM Lift June 2020

Appendix B. Photographs – RRM (continued)



Photo 21. Unloading Material for Placement June 2020



Photo 22. Compacting Lift Area with Sheepsfoot June 2020

Appendix B. Photographs – RRM (continued)



Photo 23. Stockpile Material for RRM Lifts July 2020



Photo 24. Mechanics Repairing Haul Truck July 2020

Appendix B. Photographs – RRM (continued)



Photo 25. Lift Area Prior to Compaction July 2020



Photo 26. Compacting Lift Area with Sheepsfoot August 2020

Appendix B. Photographs – RRM (*continued*)



Photo 27-Material for 2 Foot Debris Lift August 2020



Photo 28. Bulldozer Placing Material for 2 Foot Debris Lift August 2020

Appendix B. Photographs – RRM (continued)



Photo 29. Cell Operations September 2020



Photo 30. Approved Debris Lift September 2020

Appendix B. Photographs – Interim Cover



Photo 31. Interim Cover Placement November 2019



Photo 32. Interim Cover Placement November 2019

Appendix B. Photographs – Interim Cover (continued)



Photo 33. Placing Protective Cover on Interim Cover November 2019



Photo 34. Grader Placing Protective Cover on Top of Interim Cover December 2019

Appendix B. Photographs – Interim Cover (continued)



Photo 35. Interim Cover Placement December 2019



Photo 36. Interim Cover Placement June 2020

Appendix B. Photographs – Spoils Embankment



Photo 37. QC Performing Sand Cone Test September 2020



Photo 38. Constructing Spoils Embankment (Wedge) September 2020