

## **CJ Interim Completion Report – Addendum N**

### **Appendix B. Photos**

#### **Contents**

<i>Section</i>	<i>Page</i>
RRM .....	B-1
Interim Cover .....	B-12

## Appendix B. Photographs – RRM



*Photo 1. Dozer placing RRM and compactor compacting on lift above October 2023*



*Photo 2. Loader loading RRM into haul truck in cell October 2023*



## Appendix B. Photographs – RRM (*continued*)



*Photo 3. Dozer and compactor hard at work November 2023*



*Photo 4. Dust control in cell November 2023*



## Appendix B. Photographs – RRM (*continued*)



*Photo 5. Working on ramp repairs December 2023*



*Photo 6. Water truck moisture conditioning lift December 2023*

## Appendix B. Photographs – RRM (*continued*)



*Photo 7. Working in the cell with snow conditions January 2024*



*Photo 8. Cleaning snow of the lift before placement January 2024*



## Appendix B. Photographs – RRM (continued)



*Photo 9. Loader and haul trucks waiting for containers of RRM February 2024*



*Photo 10. Loading RRM with a little snow still in the ground February 2024*



## Appendix B. Photographs – RRM (*continued*)



*Photo 11. Dozer placing debris/RRM mix March 2024*



*Photo 12. Dozer cleaning snow off lifts before placement March 2024*



## Appendix B. Photographs – RRM (*continued*)



*Photo 13. Compaction between asbestos sacks April 2024*



*Photo 14. Placing containers in cell April 2024*



## Appendix B. Photographs – RRM (continued)



*Photo 15. Tires in the cell May 2024*



*Photo 16. Unloading RRM with haul truck May 2024*



## Appendix B. Photographs – RRM (*continued*)



*Photo 17. Moisture/density testing June 2024*



*Photo 18. Compactor, water truck, and haul truck working together June 2024*



## Appendix B. Photographs – RRM (continued)



*Photo 19. Placing RRM around containers July 2024*



*Photo 20. Haul truck getting ready to unload RRM for dozer to place July 2024*



## Appendix B. Photographs – RRM (*continued*)



*Photo 21. Building a new haul route August 2024*



*Photo 22. Sand cone test August 2024*



## Appendix B. Photographs – RRM (continued)



*Photo 23. Operations in the cell September 2024*



*Photo 24. Piles of RRM mixed with debris staged for placement September 2024*



## Appendix B. Photographs – Interim Cover



*Photo 25. Scarified TOW prepped for Interim Cover placement July 2024*



*Photo 26. Pushing Manco Shale for Interim Cover July 2024*



## Appendix B. Photographs – Interim Cover *(continued)*



*Photo 27. QC performing moisture/density test on Interim Cover July 2024*



*Photo 28. Water truck moisture conditioning; D6& D8 dozer placing Manco Shale July 2024*



## Appendix B. Photographs – Interim Cover (*continued*)



*Photo 29. Interim Cover completed August 2024*



*Photo 30. Loading protective cover for Interim cover August 2024*



## Appendix B. Photographs – Interim Cover (*continued*)



*Photo 31. Placing protective cover on Interim Cover August 2024*



*Photo 32. Interim Cover complete with protective cover August 2024*